National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 01/16/2003

DEN02LA072

File No. 12601		06/30/2002	Watkins, CO	Aircraft Reg No.	N6283U	Time (Local): 08:11 MDT		
Engine I Aircr Numbe Operating C Type of Fligh	Make/Model: raft Damage: or of Engines: Certificate(s): ht Operation:	1 None		Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 0	
Last Depart. Point: Destination: Airport Proximity: Airport Name: Runway Identification: Runway Length/Width (Ft): Runway Surface: Runway Surface Condition:		On Airport Front Range 26 8000 / 100 Asphalt			Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 6.00 SM Wind Dir/Speed: 220 / 009 Kts Temperature (°C): 23 Precip/Obscuration: None / Haze			
Pilot-in-Command Certificate(s)/Rating(s) Private; Single-engine Instrument Ratings None	Age: e Land	55		Т	Flight Time (Hours) Total All Aircraft: 139 Last 90 Days: 14 Total Make/Model: 59 Total Instrument Time: UnK/Nr			

The purpose of the flight was to practice touch-and-go landings. The pilot said he "forgot to put the gear down" and landed wheels up, resulting in substantial damage to the airplane.

Brief of Accident (Continued)

DEN02LA072

File No. 12601 06/30/2002 Watkins, CO Aircraft Reg No. N6283U Time (Local): 08:11 MDT

Occurrence #1: WHEELS UP LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) CHECKLIST - NOT USED - PILOT IN COMMAND

2. (C) WHEELS UP LANDING - INADVERTENT - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. the pilot's failure to use the pre-landing checklist, resulting in an inadvertent wheels up landing.